SAFETY CERTIFICATE OF BLDGS: KVS

Name of KV

Name/ No. of Building & vintage

Whether buildings are safe

: KV MHOW

: 01 & early 1980s

: Ref AGE B/R -I Office letter No.211/I/Gen/ 1/4 /E2 Dated:

06/05/2016. (Copy attached).

On Visual inspection of the bldg, it has been found that the following repairs works are urgently required to enhance the structural safety of the bldg :-

(i)Cracks are developing at various location, some of the cracks in beam and columns also.

(ii) Plaster has fallen down at various location thus revealing the reinforcement bars.

(iii) Seepage marks are present inside the administrative bldg

4. Major / Minor structural repair project by Vidyalaya

5. Major / Minor structural repairs are done by sponsoring agency during current year 2015-16

6. Additional requirement of classrooms/ Accomodation are provided by sponsoring agency.

7. Space of the school is adequate

8. Whether water / electric supply and sanitary facilities are provided by sponsoring agency.

Station: MHOW

:NA

:NA

:NA

:NA

Only water supply is provided

by MES.

AE (CIVIL)

AGE B/R -I Mhow

Date: 06/05/2016

COUNTERSIGN

(V.K TIWARI, IDSE)

EE (SG)

Tison Engineer(m) Inf School, Mhow